

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 9/30/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S08AA_005MH

Test ID: D1032-020004

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Manhole	S08AA_005MH
0			Start of Survey	
0			Water Level	
80	11		Broken	
80			Dye Test Visible	DYE SEEN AT BROKEN PIPE
83.80000305			Dye Test Visible	DYE SEEN AT JOINT & BROKEN PIPE
87.80000305			Abandoned Survey	DTE TEST IS COMPLETE